

POOR LEGIBILITY

ONE OR MORE PAGES IN THIS DOCUMENT ARE DIFFICULT TO READ
DUE TO THE QUALITY OF THE ORIGINAL

Waipio Peninsula Remedial Investigation Report
August 2002


Prepared For:

Oahu Sugar Company
700 Bishop Street, No. 501
Honolulu, Hawaii 96813

REMEDIAL INVESTIGATION REPORT
FORMER PESTICIDE MIXING PLANT
WAIPIO PENINSULA
WAIPAHU, HAWAII
HID 984467605

BES Job No. 5224

August 2002



Patrick H. Lineberger
Senior Geologist



Kevin Kennedy
Vice President BEI Environmental Services

BEI Environmental Services
311B Pacific Street
Honolulu, Hawaii 96817
(808) 535-6055

TABLE OF CONTENTS

Title Page	i
Signature Page.....	ii
Table Of Contents	iii
PHOTOGRAPHS	vii
1.0 EXECUTIVE SUMMARY.....	1
2.0 INTRODUCTION.....	3
3.0 SCOPE OF WORK.....	4
4.0 SITE BACKGROUND	6
4.1 Site Description.....	6
4.2 Site History	7
4.3 Previous Investigation.....	7
4.4 Climate.....	8
4.5 Geology.....	8
4.6 Hydrology	9
5.0 DATA QUALITY OBJECTIVES	12
6.0 REGULATORY REQUIREMENTS AND ACTION LEVELS	13
6.1 Chemicals Of Concern.....	13
6.2 Dioxin Toxicity Equivalent Factors and Quotients.....	14
7.0 FIELD ACTIVITIES.....	16
7.1 Site Safety & Health Plan (SSHP)	16
7.1.1 Establishing The Work Zones.....	16
7.2 Site planning	17
7.2.1 Site Access	17
7.2.2 Pre-Field Site Visit.....	17
7.2.3 Soil Sample Locations	17
7.2.4 Monitoring Well Locations.....	18
7.3 Soil Sample Collection Methodology.....	19
7.3.1 Surface Soil Collection	19
7.3.1.1 Soil Sampling for Quality Control (QC).....	19
7.3.2 Subsurface Soil Collection.....	20
7.3.2.1 Soil Sampling for Quality Control (QC).....	20
7.3.2.2 Drill Rig Methodology.....	20
7.3.2.3 Borehole Sampling.....	21
7.3.2.4 Borehole Logging.....	21
7.3.2.5 Decontamination	22
7.3.3 Sample Laboratory Analytical Requirements	22
7.3.4 Sample Laboratory Analyses	22